



VS-KB30 Firmware Release Note

Version Difference:

Model	VS-KB30	VS-KB30,V01	VS-KB30,V2
Product Label			
S/N	V96XXXXXX	VC2XXXXXX	VCUXXXXXX
FW ver.	Master : 0.X.XL Webpage : v2.X.X or vA.1.X	Master : 2.X.XL Webpage : vA.1.X	Master : 3.X.XL Webpage : vA.1.X

1 VS-KB30,V2

1.1 Master

Release Date	Version	Description	Note
2023/06/06	3.1.4L	Bugs fixed and Improvements. - Fixed VISCA over IP cannot change Shutter/Iris. - Fixed issue displays wrong IP address. - Fixed the connection randomly drop issue.	Add new module : VC-A62/VC-A71P-HN
2022/11/15	3.1.0L	Bugs fixed that camera connect failed issue.	
2022/09/22	3.0.9L	Bug Fixes and Improvements Fixed issue of display incorrect IP.	
2022/02/15	3.0.6L	First version.	

1.2 Webpage

Release Date	Version	Description	Note
2022/02/22	vA.1.5	Add Auto Tracking/Auto Framing switch and ON/OFF button.	

2 VS-KB30,V01

2.1 Master

Release Date	Version	Description	Note
2022/11/15	2.1.4L	Bugs fixed that camera connect failed issue.	
2022/09/22	2.1.3L	Fixed issue of display incorrect Shutter Speed value.	
2022/07/21	2.1.1L	Bug Fixes and Improvements 1. Fixed issue of display incorrect IP.	
2022/02/22	2.1.0L	Add Auto Tracking/Auto Framing switch and ON/OFF button.	
2021/09/16	2.0.8L	The Iris/Shutter R/B gain value will be displayed when using VISCA over IP connection.	
2021/07/01	2.0.6L	New Features 1. Added Tally light control switch. Bug Fixes and Improvements 1. Fixed issue of controlling cameras by VISCA over IP.	
2021/05/10	2.0.1L	First version.	

2.2 Webpage

Release Date	Version	Description	Note
2022/02/22	vA.1.5	Add Auto Tracking/Auto Framing switch and ON/OFF button.	
2021/05/10	vA.1.4	Compatible with VS-KB30,V01	

3 VS-KB30

3.1 Master

Release Date	Version	Description	Note
2022/11/15	1.0.2L	Bugs fixed that camera connect failed issue.	
2022/07/21	1.0.1L	Bug Fixes and Improvements 1. Fixed issue of display incorrect IP.	
2022/02/22	1.0.0L	Add Auto Tracking/Auto Framing switch and ON/OFF button.	
2021/09/16	0.9.8L	The Iris/Shutter R/B gain value will be displayed when using VISCA over IP connection.	
2021/07/14	0.9.4L	New Features 1. Added Tally light control switch. Bug Fixes and Improvements 1. Fixed issue of controlling cameras by VISCA over IP.	
2021/03/09	0.8.9L	Improve the switching speed between multiple cameras: from 3 sec to 1.5 sec.	
2020/11/20	0.8.7L	Improved OLED protection mechanism.	
2020/11/20	0.8.6L	Improve the switching speed between multiple cameras	
2020/05/15	0.8.5L	Bugs fixed.	
2020/02/04	0.8.3L	Modified the speed of Manual Focus.	
2019/09/20	0.7.9L	Bugs fixed that Pelco D preload setting abnormal when connecting with VC-A50P.	
2019/07/03	0.7.6L	Bugs fixed that shutter value not match when connect with VC-A70H.	
2019/04/02	0.6.9L	DHCP default changes to On.	
2019/01/10	0.6.7L	First version.	

3.2 Webpage

Release Date	Version	Description	Note
2021/03/09	v2.9.3 / vA.1.4	Improve the switching speed between multiple cameras: from 3 sec to 1.5 sec.	
2020/11/20	v2.9.2	Fixed switching camera issue.	
2019/09/20	v2.8.1	Bugs fixed that Pelco D preload setting abnormal when connecting with VC-A50P.	
2019/07/03	v2.6.5	Bugs fixed that shutter value not match when connect with VC-A70H.	
2019/01/10	v2.5	First version.	

